


Figure 6

Mid Incline THP (05_123)
Watershed Analysis Deep-Seated Landslide Inventory
Unit 3

1 inch equals 250 feet



- | | | |
|---------------------------|---------------------|--|
| PALCO HCP/SYP Timberlands | Class 1 Watercourse | Paved Road |
| Other PALCO Timberlands | Class 2 Watercourse | Rocked Road |
| Other Private Ownership | Class 3 Watercourse | Dirt Road |
| CC | | Dirt Jeep Trails |
| Partial Cut | | Proposed Roads |
| No Cut | | Closed, Decommissioned, or Abandoned Roads |

- Crown of Deep-Seated Landslides
- Hazard for Reactivation or Acceleration of Movement**
- | | |
|--|-------------------------------------|
| | N/A (landslides in grassland areas) |
| | Very Low |
| | Low |
| | Low to Moderate |
| | Moderate |
| | High |

